



Engine Coolant Crossover Pipe
CRP Part No. CHP0908

Applications:

Multiple applications for
Land Rover

For details, see showmetheparts.com/crp



Land Rover OE reference LR090630. Designed to be a direct-fit replacement for easy installation. Made to strict engineering quality standards. Resistant to heat, salt, road debris, oil, and other contaminants.



Engine Coolant Pipe
CRP Part No. CHP0910

Applications:

Multiple applications for
Land Rover

For details, see showmetheparts.com/crp



Land Rover OE reference LR050935. Crossover pipe to cylinder block is designed as a direct-fit replacement to ensure trouble-free proper installation. Made to strict engineering quality standards.



New HPS Rack & Pinion
CRP Part No. 3315N

Applications:

BMW X3 2004-10



First-to-market new HPS rack and pinion supplied with inner tie rods and new bellows secured by OE stainless steel clamps to keep dirt and debris out, preventing premature failure. Matches OE design specifications. Sold without core charge.



New HPS Rack & Pinion
CRP Part No. 3313N

Applications:

Multiple applications for
BMW

For details, see showmetheparts.com/crp



First-to-market new HPS rack and pinion engineered to meet or exceed OE specifications in performance, fit, and function. To ensure proper operation, each unit undergoes thorough inspection and testing procedures. Sold without core charge.



New HPS Pump
CRP Part No. 50491N

Applications:

Multiple applications for
Mercedes-Benz

For details, see showmetheparts.com/crp



First-to-market new HPS pump engineered to meet or exceed OE specifications. Return pipe included. Sold without core charge. It is highly recommended to replace steering fluid reservoir when replacing pump. Clogged reservoirs can starve the replacement pump.



New EPS Manual Rack & Pinion
CRP Part No. 4613N

Applications:

Hyundai Santa Fe 3.3L 2013-19



First-to-market new EPS rack and pinion supplied with inner tie rods and new bellows secured by OE stainless steel clamps to keep dirt and debris out, preventing premature failure. 100% inspected and tested. Sold without core charge.

ECAT data may not be available for parts shown for 90 days after initial announcement.

**FOR MORE INFORMATION CALL 800.526.4066 AND SPEAK WITH A CRP REPRESENTATIVE
OR VISIT CRPAUTOMOTIVE.COM**