


This Just In!

VALVE COVERS & KITS



Part No. VCE0103 (Valve Cover only)
Part No. VCK0103 (Kit)



Part No. VCE0104 (Valve Cover only)
Part No. VCK0104 (Kit)



Part No. VCE0105 (Valve Cover only)
Part No. VCK0105 (Kit)



Part No. VCE0106 (Valve Cover only)
Part No. VCK0106 (Kit)



Effective Date:
February 21, 2020

REIN VALVE COVERS & VALVE COVER KITS

Data available through [Activant/Epicor](#), [WHI](#), or [ShowMeTheParts.com](#)

In the last 20 years, we have seen more vehicle manufacturers use plastic components under the hood of vehicles. There are significant weight and development savings that these components offer, but there are some disadvantages. The main shortcoming we've seen is that the life expectancy of these components is much shorter than their aluminum or steel counterparts.

Along with warping and cracking, many valve covers also have integrated breather valves that can fail, which leads to drivability issues and in most cases a check engine light. The only repair for this situation is often a new valve cover. This can be quite costly and as vehicles age, could become too expensive based on the value of the vehicle.

Rein Automotive now offers alternatives to the dealer component on valve covers with additional coverage being announced over the next six months. These Rein valve covers were developed and tested to offer technicians an excellent solution to a repair that is becoming much more frequent.

Along with individual valve covers, kits are available inclusive of the valve cover and many of the additional components that are commonly replaced at the same time, like oil caps, breather hoses, and in some cases, single use hardware.



Part No. VCE0102 (Valve Cover only)
Part No. VCK0102 (Kit w/ sensor)
Part No. VCK0102B (Kit w/o sensor)

CRP Automotive
35 Commerce Drive
Cranbury, NJ 08512
Tel. 609.578.4100 800.526.4066
Email: info@crpindustries.com
Web: www.crpautomotive.com



Rein Part No.	Applications	VIO US	VIO CA	ETA Date
VCE0101 (Valve Cover Only)	BMW 135i 3.0L 2011-13; 135iS 3.0L 2013; 335i 3.0L 2011-15; 335i GT 3.0L 2014-16; 435i 3.0L 2014-16; 435i GRAN COUPE 3.0L 2015-16; 535i 3.0L 2011-16; 535i GT 3.0L 2010-17; 640i 3.0L 2012-18; 640i GRAN COUPE 3.0L 2013-19; 740i / 740Li 3.0L 2013-15; ACTIVEHYBRID 3 3.0L 2013-15; ACTIVEHYBRID 5 3.0L 2012-16; ACTIVEHYBRID 7 3.0L 2013-15; M2 3.0L 2016-19; M235i 3.0L 2014-16; X1 3.0L 2013-15; X3 3.0L 2011-17; X4 3.0L 2015-18; X5 3.0L Gas 2011-18; X6 3.0L 2011-19	24,558	4,144	Summer 2020
VCK0101 (Kit)	BMW 135i 3.0L 2011-13; 135iS 3.0L 2013; 335i 3.0L 2011-15; 335i GT 3.0L 2014-16; 535i 3.0L 2011-16; 535i GT 3.0L 2010-17; 640i 3.0L 2012-18; 640i GRAN COUPE 3.0L 2013-19; ACTIVEHYBRID 5 3.0L 2012-16; X1 3.0L 2013-15; X3 3.0L 2011-17; X4 3.0L 2015-18; X5 3.0L Gas 2011-18; X6 3.0L 2011-19			
VCE0102 (Valve Cover Only)	BMW 128i 3.0L 2008-13; 323i 2.5L 2007-11 (CA); 328i 3.0L 2007-13; 328Xi 3.0L 2007-08; 528i 3.0L 2008-10; 528Xi 3.0L 2008; X3 3.0L 2007-10; X3 3.0L 2011-12; X5 3.0L 2007-08; X5 2009-3.0L Gas 2010; Z4 3.0L 2007; Z4 3.0L 2008; Z4 3.0L 2009-11	645,582	75,881	Available Now
VCK0102 (Kit w/ sensor)	BMW 128i 3.0L 2008-13; 323i 2.5L 2007-11 (CA); 328i 3.0L 2007-13; 328Xi 3.0L 2007-08; 528i 3.0L 2008-11; 528Xi 3.0L 2008; X3 3.0L 2007-10; X5 3.0L 2007-08; X5 2009-3.0L Gas 2010; Z4 3.0L 2007; Z4 3.0L 2008; Z4 3.0L 2009-11	595,133	70,270	
VCE0103 (Valve Cover Only)	BMW 228i 2.0L 2014-16; 320i 2.0L 2012 (CA); 320i 2.0L 2013-18; 328i 2.0L 2016; 328i 2.0L 2012-13; 328i 2.0L 2014-15; 328i 2.0L 2014-16; 328i GT 2.0L 2014; 328i GT 2.0L 2015-16; 428i 2.0L 2014-16; 428i GRAN COUPE 2.0L 2015-16; 428i GRAN COUPE 2.0L 2015-16; 528i 2.0L 2012-16; X1 2.0L 2012 (CA, MX); X1 2.0L 2013-15; X3 2.0L 2013-14; X3 2.0L Gas 2015-17; X4 2.0L 2015-18; X5 2.0L 2016-18; Z4 2.0L 2012-16	957,583	100,220	Available Now
VCK0103 (Kit)				
VCE0104 (Valve Cover Only)	BMW 1 SERIES M 3.0L 2011; 135i 3.0L 2008-10; 335i 3.0L 2007-10; 335iS 3.0L 2011-13; 335Xi 3.0L 2007-08; 535i 3.0L 2008-10; 535Xi 3.0L 2008; 740i / 740Li 3.0L 2011-12; X6 3.0L 2008-10; Z4 3.0L 2009-16	5,391	537	Available Now
VCK0104 (Kit)	BMW 1 SERIES M 3.0L 2011; 135i 3.0L 2008-10; 335i 3.0L 2007-10; 335iS 3.0L 2011-13; 335Xi 3.0L 2007-08; 535i 3.0L 2008-10; Z4 3.0L 2009-16			
VCE0105 (Valve Cover Only)	BMW 320i 2.2L 2001-03 (CA, MX); 323Ci 2.5L 2000; 323i 2.5L 1999-00; 325Ci / 325i / 325Xi 2.5L 2001-03; 328Ci 2.8L 2000; 328i 2.8L 1999-00; 330Ci / 330i / 330Xi 3.0L 2001-03; 525i 2.5L 2001-03; 528i 2.8L 1999-00; 530i 3.0L 2001-03; X5 3.0L 2001-03; Z3 2.8L 1999-00; Z3 2.5L 1999-02; Z3 3.0L 2001-02	479,870	26,546	Available Now
VCK0105 (Kit)				
VCE0106 (Valve Cover Only)	BMW 320i 2.2L 2003-05 (CA, MX); 325Ci 2.5L 2003-06; 325i / 325Xi 2.5L 2003-05; 330Ci 3.0L 2003-06; 330i / 330Xi 3.0L 2003-05; 525i 2.5L 2003-05; 530i 3.0L 2003-05; X3 2.5L 2006 (CA, MX); X3 2.5L 2004-05; X3 3.0L 2004-06; X5 3.0L 2003-06; Z4 2.5L 2003-05; Z4 3.0L 2003-05	469,008	33,973	Available Now
VCK0106 (Kit)	BMW 320i 2.2L 2003-05 (CA, MX); 325Ci 2.5L 2003-06; 325i / 325Xi 2.5L 2003-05; 330Ci 3.0L 2003-06; 330i / 330Xi 3.0L 2003-05; 525i 2.5L 2003-05; 530i 3.0L 2003-05; X3 2.5L 2006 (CA, MX); X3 2.5L 2004-05; X3 3.0L 2004-06; X5 3.0L 2003-04; Z4 2.5L 2003-05; Z4 3.0L 2003-05	437,665	31,431	