

This Just In!



Effective Date:
October 1, 2020

REIN AUTOMOTIVE UPGRADED BMW ENGINE COOLANT HOSES

Data available through [Activant/Epicor](#), [WHI](#), or [ShowMeTheParts.com](#)

The engine coolant hose on many 2008-2014 BMW models with V8 engines is known for failing. The plastic Y connector that is used by the OEM to connect the three rubber hoses fails over time. Also, the hose is located underneath the intake manifold on these vehicles which can make the replacement process very time consuming.

Rein Automotive's upgraded BMW engine coolant hoses (CRP Part Nos. CHU0554 and CHU0555) utilize a metal Y fitting to ensure a longer, problem-free service life for the part. Professional repair technicians can have confidence when using these Rein Automotive parts that they have all of the components needed to complete the replacement quickly and efficiently.

FEATURES & BENEFITS:

- Direct replacement for the OE hose that needs to be replaced
- All needed clamps are included with this hose for the installation
- Upgraded and installed metal Y fitting provided for longer life than the OE



CRP Part No.	OE Reference	Applications	VIO US	VIO Canada	ETA Date
CHU0554	17127536236	BMW X5 V8 4.8L 2007-10	20,256	2,332	10/26/20
CHU0555	17127576363	BMW 550i V8 4.4L 2011-13; 550i GT V8 4.4L 2010-12; 650i V8 4.4L 2012; 750i / 750Li V8 4.4L 2009-12; X5 V8 4.4L 2011-13; X6 V8 4.4L 2008-14	57,578	6,176	10/26/20

CRP Automotive
35 Commerce Drive
Cranbury, NJ 08512

Tel. 609.578.4100 800.526.4066
Email: info@crpindustries.com
Web: www.crpautomotive.com

