This Just In!

KITS













Updated: January 7, 2021

REIN BMW PROBLEM SOLVER HOSE KITS

Data available through Activant/Epicor, WHI, or ShowMeTheParts.com

The Problem:

In some BMW's, the engine supply coolant pump assembly connects the cylinder head to the water pump. The assembly consists of a metal pipe that connects to the cylinder head and a rubber elbow that connects to the water pump. As the vehicle ages, the rubber elbow can degrade and leak or can be changed as a preventative measure when the water pump is replaced. During a repair, the technician must remove multiple exhaust system components to access the cylinder head portion of the assembly. This can add hours of labor time to the job.



Based on feedback from CRP Automotive Innovation Council members, the most failure prone component of the assembly is the rubber elbow. Rein now offers a kit that includes a custom designed elbow and the clamps needed to efficiently remove the old elbow and install the new one in much less time than it would normally take to change the whole assembly. Rein's kit will save the technician hours of labor by not having to remove multiple exhaust system components, making the repair a more cost effective option versus buying the entire OE hose assembly.



CRP Automotive

35 Commerce Drive Cranbury, NJ 08512 Tel. 609.578.4100 800.526.4066 Email: info@crpindustries.com





Kit OE Interchange

Rein Part No.	OE Part No.	Applications	VIO US	VIO CA	Total VIO
CHE0494	11537558523	BMW 1 SERIES M 3.0L 2011; 135I 3.0L 2008-2010; 335I 3.0L 2007-2013; 335IS 3.0L 2011-2013; 335XI 3.0L 2007-2008; Z4 3.0L 2009-2014	173,524	21,224	194,748
CHE0495	SUPERSEDING TO CHE0494				
CHE0496	11537516414	BMW 128I 3.0L 2008-2013; 325I / 325XI 3.0L 2006; 328I 3.0L 2007-2013; 328XI 3.0L 2007-2008; 330I / 330XI 3.0L 2006; 525I / 525XI 3.0L 2006-2007; 528I 3.0L 2008-2010; 528XI 3.0L 2008; 530I / 530XI 3.0L 2006-2007; X3 3.0L 2009-2010; Z4 3.0L 2006-2011	746,534	68,268	814,802
CHE0497	11537535829	BMW 128I 3.0L 2008-2013; 325I / 325XI 3.0L 2006; 328I 3.0L 2007-2013; 328XI 3.0L 2007-2008; 330I / 330XI 3.0L 2006; X3 3.0L 2007-2010	620,553	63,059	683,612
CHE0634	11537560530	BMW 535I 3.0L 2008-2010; 535XI 3.0L 2008	45,420	2,495	47,915
CHE0682	11537584630	BMW X5 3.0L 2011-13 Gas; X6 3.0L 2011-14	83,724	9.821	93,545

CRP Automotive

Cranbury, NJ 08512
Tel. 609.578.4100 800.526.4066
Email: info@crpindustries.com

