## This Just In!




Effective Date: November 25, 2022

## REIN UPGRADED TURBO COOLANT RETURN LINE FOR BMW

Data available through Activant/Epicor, WHI, or ShowMeTheParts.com

Turbocharger coolant lines are exposed to the high operating temperatures of turbocharger systems and heat cycling. These extreme conditions cause hoses to wear, resulting in parts of the hose becoming brittle. Currently, many OE manufacturers use plastic pipes, fittings, and quick connectors that are failure prone. When turbocharger coolant hose assemblies contain plastic components, premature wear is likely and prompts the need for replacement.





equipped with the twin turbocharged V8 4.4L engines (CRP Part No. CHU0755). The OE version of this hose features a plastic T-fitting, which is known to fail. The upgraded Rein version of this coolant line includes a **metal T-fitting** that eliminates the common failure point to ensure a longer, problem-free life.

## **FEATURES & BENEFITS:**

- Direct replacement for OE hoses includes all components and branches
- Upgraded quality hoses and assemblies ensure long, problem-free service life
- All clamps needed for installation are included with each hose/assembly

CRP Automotive

35 Commerce Drive Cranbury, NJ 08512 Tel. 609.578.4100 800.526.4066 Email: info@craindustries.com





## **Applications**

Rein Part No.	OE Reference	Applications	VIO US	VIO Canada	ETA Date
CHU0755	11537637059	BMW X5 V8 4.4L 2014-18; X6 V8 4.4L 2015-19	29,428	2,612	Available Now

35 Commerce Drive Cranbury, NJ 08512 Tel. 609.578.4100 800.526.4066 Email: info@craindustries.com

