

This Just In!



*Effective Date:
November 15, 2022*

REIN OE ANTI-FOG SENSOR KIT FOR BMW

Data available through Activant/Epicor, WHI, or ShowMeTheParts.com

The anti-fog sensor in popular BMW models is responsible for detecting moisture on the inside of the windshield so that the HVAC system can automatically reduce the fogging effect that can occur. Replacing a faulty anti-fog sensor requires precise positioning of the new sensor, as it sits at the base of the rearview mirror. Proper placement of the sensor ensures that the automatic climate control system will work as per design.

CRP Automotive now offers a Rein-branded OE Anti-Fog Sensor Kit (CRP Part No. ELM0087) for this repair on popular BMW applications. This **first-to-market solution kit** comes complete with the OE anti-fog/condensation sensor and OE installation tool, both manufactured in Germany by the OE manufacturer. Including the OE installation tool in this kit provides the necessary components to allow a professional repair technician to complete this repair efficiently in both time and cost.



CRP Part No. ELM0087

FEATURES & BENEFITS:

- Ensures proper installation of a faulty anti-fog sensor
- First-to-market solution kit includes sensor and installation tool
- Manufactured in Germany by the OE manufacturer
- 2 year / 24,000 mile warranty

CRP Automotive
35 Commerce Drive
Cranbury, NJ 08512

Tel. 609.578.4100 800.526.4066
Email: info@crpindustries.com
Web: www.crpautomotive.com



Rein Part No.	OE Reference	Applications	VIO US	VIO Canada	ETA Date
ELM0087	64116928326	BMW 135I 3.0L 2008-13; 135IS 3.0L 2013; 1 SERIES M 3.0L 2011; 323I 2.5L 2006-11 (CA); 325I / 325XI 3.0L 2006; 328I 3.0L 2007-13; 328I XDRIVE 3.0L 2009-13; 328XI 3.0L 2007-08; 330I / 330XI 3.0L 2006; 335D 3.0L DIESEL 2009-11; 335I 3.0L 2007-13; 335I XDRIVE 3.0L 2009-13; 335IS 3.0L 2011-13; 335XI 3.0L 2007-08; 525I 2.5L 2004-05; 525I 3.0L 2006-07; 525XI 3.0L 2006-07; 528I 3.0L 2009-10; 528I XDRIVE 3.0L 2009-10; 528XI 3.0L 2008; 530I 3.0L 2004-07; 530XI 3.0L 2006-07; 535I 3.0L 2008-10; 535I XDRIVE 3.0L 2009-10; 535XI 3.0L 2008; 545I 4.4L 2004-05; 550I 4.8L 2006-10; 645CI 4.4L 2004-05; 650I 4.8L 2006-10; 650I NEW 4.8L 2006-10; 745LI 4.4L 2002-05; 750LI 4.8L 2006-08; 750LI NEW 4.8L 2006-08; 760LI 6.0L 2003-08; M3 4.0L 2008-13; M5 5.0L 2006-10; M6 5.0L 2006-10; X1 2.0L 2013-15; X1 2.0L 2012 (CA, MX); X1 3.0L 2013-15; X5 3.0L DIESEL 2009-13; X5 3.0L GAS 2009-13; X5 3.0L 2007-08; X5 4.4L 2010-13; X5 4.8L 2007-10; X6 3.0L 2008-14; X6 4.4L 2008-14; Z4 2.0L 2012-16; Z4 3.0L 2009-16; ROLLS ROYCE PHANTOM 6.7L 2004-17	1,152,416	130,200	Available Now