



# AAE NEW HPS RACKS & PUMPS

- **New** Hydraulic Power Steering units for popular Domestic and Import vehicles
- 100% tested in the USA
- No core charge
- Inventory available for immediate shipment

CRP Part No.	Product	OE Numbers	Make
5760N	NEW P/S PUMP	5610ORDJA01RM, 56110PVJA01, 56110R70A12, 56110RDJA02, 56110RGLA03, 56110RJEA02, 56110RN0A03, 56110RYEA05	ACURA, HONDA
5777N	NEW P/S PUMP	56110RCAA02	HONDA
5776N	NEW P/S PUMP	56110RAAA04, 56110RBBE01	ACURA, HONDA
3179N	NEW RACK & PINION	442500C010, 442500C030, 442500C041	TOYOTA
5459N	NEW P/S PUMP	4432007012, 4432033140, 4432048040	LEXUS, TOYOTA
5892N	NEW P/S PUMP	491101AA0A, 49110ZX02A, 49110ZX70A	NISSAN
5339N	NEW P/S PUMP	56110P8FA01, 56110P8FA02	HONDA
5618N	NEW P/S PUMP	34430AG03B, 34430AG0419L, 34430AG051, 34430FG0009L	SUBARU
3578N	NEW RACK & PINION	4425008041	TOYOTA
3470N	NEW RACK & PINION	4425007011, 4425007062	LEXUS, TOYOTA

**CONTACT YOUR CRP  
REPRESENTATIVE AT  
800.526.4066.**

Visit our online catalog at  
[showmetheparts.com/crp](http://showmetheparts.com/crp).





CRP Part No.	Product	OE Numbers	Make
3676N	NEW RACK & PINION	4420060170	LEXUS, TOYOTA
5706N	NEW P/S PUMP	06561PGK505RM, 56110P8EA01	ACURA, HONDA
3050N	NEW RACK & PINION	49001ZH50A	INFINITI, NISSAN
3375N	NEW RACK & PINION	4420048090, 4420048180, 442500E012	LEXUS, TOYOTA
3923N	NEW RACK & PINION	53601SA02, 53601SA12, 53601SA51, 53601SA61	HONDA
3820N	NEW RACK & PINION	53601SHJA06, 53601SHJA84, 53601SHJA86	HONDA
3871N	NEW RACK & PINION	4425006141, 4425007101	TOYOTA
5999N	NEW P/S PUMP	0054462201, 0054662001	MERCEDES-BENZ
3124N	NEW RACK & PINION	53601TA0A02, 53601TA5A02, 53601TA6A02, 53601TE0A02, 53601TE1A02	HONDA
64219N	NEW RACK & PINION	19330564	CHEVROLET, GMC
3120N	NEW RACK & PINION	53601S10A01, 53601S10A02, 53601S10A03	HONDA
3751N	NEW RACK & PINION	49001ZB000	NISSAN
64359N	NEW RACK & PINION	52122302AD, 52855758AH	CHRYSLER, DODGE
7817N	NEW GEAR BOX	6C3Z3504AB, 7C3Z3504ARM, 7C3Z3504BRM, C3Z3504BRM	FORD
3473N	NEW RACK & PINION	4420035061, 4420035070	LEXUS, TOYOTA
5598N	NEW P/S PUMP	4431028240, 443248020	LEXUS, TOYOTA
3157N	NEW RACK & PINION	49001ZM71B	NISSAN
3184N	NEW RACK & PINION	1J1422061N, 1J1422075EX, 1J1422075P	VOLKSWAGEN
7820N	NEW GEAR BOX	8C3Z3504ARM, 8C3Z3504CRM	FORD
3270N	NEW RACK & PINION	4425006011, 4425006013, 4425006014, 4425033014	TOYOTA
3331N	NEW RACK & PINION	34110SA080	SUBARU
4577N	NEW RACK & PINION	4551042240	TOYOTA
3658N	NEW RACK & PINION	49001CB810, 49001CC210	NISSAN
4223N	NEW RACK & PINION	53040SR3A01	HONDA
3210N	NEW RACK & PINION	32136751745	BMW
5696N	NEW P/S PUMP	0024669701, 0024669801, 0024669901	MERCEDES-BENZ
3813N	NEW RACK & PINION	1634600725, 163460072588	MERCEDES.BENZ
3495N	NEW RACK & PINION	36050281, 36050357, 36050358	VOLVO
3618N	NEW RACK & PINION	68088212AA, 9064600800	DODGE, FREIGHTLINER, MERCEDES-BENZ
3202N	NEW RACK & PINION	8E1422054EX	AUDI
3579N	NEW RACK & PINION	4425035080	TOYOTA
5353N	NEW P/S PUMP	0024668201, 002466820188	MERCEDES-BENZ
3004N	NEW RACK & PINION	8N1422061DX	AUDI
3493N	NEW RACK & PINION	8601801	VOLVO
3985N	NEW RACK & PINION	3B1422052L, 3B1422052MX, 3B1422053X, 4B0419801G, 8D1422052LX, 8D1422053AV	AUDI, VOLKSWAGEN

**CONTACT YOUR CRP REPRESENTATIVE  
AT 800.526.4066.**

Visit our online catalog at [showmetheparts.com/crp](http://showmetheparts.com/crp).

