



Upgraded Oil Filter Housing CRP Part No. HEU0116

Applications:

Multiple applications for BMW B58 engines



OE reference 11428583895. Full aluminum construction eliminates common causes of failure and improves durability for a longer, problem-free service life. Includes pre-installed oil cooler, OEM oil filter, and mounting hardware. High-performance gasket materials used throughout.



Breather Valve Repair Kit CRP Part No. ABF0215

Applications:

Multiple applications for Mercedes-Benz 2012-19 V6 3.5L engines



OE reference 2760100331. First-to-market problem solver kit is a direct-fit replacement that reduces installation time. Includes all components needed for repair, including the cap, diaphragm, and spring.



Turbo Coolant Line Solution CRP Part No. CHT0964B

Applications:

Multiple applications for BMW B58 engines



OE reference 11538666857. Addresses common OE failure point in the turbocharger cooling circuit. Design allows technicians to remove OE clamp and replace only the failed hose section, avoiding full hose assembly replacement. Includes pre-opened clamp for easy installation and consistent sealing.



Breather Valve CRP Part No. ABH0372

Applications:

Multiple applications for Audi & Volkswagen 4 Cyl. 1.8L & 2.0L engines



OE references 06H906517AE and 06H906317AE. Designed as a direct-fit replacement for easy installation. Identical to the OEM part. Restores proper system function. Manufactured with high-quality materials.



Upgraded Engine Water Hoses with Metal Flanges CRP Part Nos. CHU0542, CHU0546, CHU0552, CHU0566

Applications:

Multiple applications for BMW



Part No. CHU0542
OE Ref. 11537603514



Part No. CHU0546
OE Ref. 11537580969



Part No. CHU0552
OE Ref. 11537552339



Part No. CHU0566
OE Ref. 11537550062

Direct-fit OE replacement hoses featuring a metal connector (CHC0609), which upgrades a common coolant hose failure point. Prevents leaks and comebacks from reusing old quick connectors and o-rings. No cutting or refitting necessary. Reduces installation time. Resistant to heat, salt, road debris, oil, and other contaminants.

ECAT data may not be available for parts shown for 90 days after initial announcement.

**FOR MORE INFORMATION ON THESE PRODUCTS,
SCAN THE QR CODE OR VISIT CRPAUTOMOTIVE.COM**





Engine Oil Pan Kits

CRP Part Nos. **ESK0228, ESK0229, ESK0230, ESK0242, ESK0243**

Applications:

Multiple applications for Mercedes-Benz V6 & V8 engines



Part No. **ESK0228**
OE Ref. 2720100126



Part No. **ESK0229**
OE Ref. 2760100528



Part No. **ESK0230**
OE Ref. 2720100828

Direct-fit, OE-quality oil pans made from premium materials. Backed by 2-year or 24,000 mile warranty. Select oil pans include new drain plugs and the needed sealant, o-rings, or gaskets for installation.



Aluminum Engine Oil Pan Kits

CRP Part Nos. **ESK0231 & ESK0241**

Applications:

Multiple applications for BMW 6 Cyl. 3.0L engines & MINI 4 Cyl. 1.6L engines



Part No. **ESK0231**
OE Ref. 11137550483

Direct-fit, OE-quality oil pan kits made from premium materials. Backed by a 2-year or 24,000-mile warranty. Each kit includes new drain plugs and the required sealant, O-rings, or gaskets for installation.



Engine Oil Pan Kit

CRP Part No. **ESK0240**

Applications:

Multiple applications for Audi 4 Cyl. 2.0L engines



OE reference 06L103598R. Direct-fit, OE-quality oil pan kits made from premium materials. Backed by a 2-year or 24,000-mile warranty. Includes new drain plugs and the required sealant, O-rings, or gaskets for installation.



Fuel Hose Assembly

CRP Part No. **RFH0008**

Applications:

BMW 525i 3.0L 2006-07; 525Xi 3.0L 2006-07; 528i 3.0L 2008-11; 528i xDrive 3.0L 2009-10; 528Xi 3.0L 2008; 530i 3.0L 2006-07; 530Xi 3.0L 2006-07



OE reference 13537537964. First-to-market, OE-quality direct-fit replacement for easy installation. Ensures proper flow and ventilation is maintained in vehicle's fuel system.



New HPS Fluid Reservoir

CRP Part Nos. **RES-0186 & RES-0187**

Applications:

Multiple applications for BMW



Part No. **RES-0186**

OE references 32416782286 and 32416782942. RES-0186 is first-to-market. Direct-fit replacement for easy installation. Faulty or damaged reservoirs can allow air to enter the hydraulic system causing noise and premature failures. Includes reservoir and reservoir cap.

ECAT data may not be available for parts shown for 90 days after initial announcement.

**FOR MORE INFORMATION ON THESE PRODUCTS,
SCAN THE QR CODE OR VISIT CRPAUTOMOTIVE.COM**

