

This Just In!




Effective Date:
May 1, 2019

REIN AUTOMOTIVE DRIVE SYSTEM SERVICE KITS

Data available through *Activant/Epicor, WHI, or ShowMeTheParts.com*



Solution Kits for Vehicles with Timing and Accessory Belts



Solution Kits for Vehicles with Accessory Belts Only

Modern automotive drive systems are complex and include various components. The current high quality materials used to manufacture accessory drive belts is resulting in increased durability and longer service life. However, when these drive systems require service, many technicians choose to change all the components at one time due to the mileage of the vehicle. Since this is often done at the same time as timing belt change, it is ideal to be able to source all necessary components together from one place.

CRP Automotive now offers Rein Automotive Drive System Service Kits that cover the entire drive system of the vehicle including accessory and, if applicable, timing components to make sourcing high quality parts for these critical jobs even easier. If a vehicle has a timing belt, the appropriate Rein kit includes the timing belt and all other necessary components along with the accessory drive belt and its associated components. For a vehicle with a timing chain, the appropriate Rein kit includes the belt and all of the components associated with the accessory drive system, including the water pump.

Rein Automotive Drive System Service Kits offer professional repair technicians an excellent solution for a complete service of a vehicle's drive system to save time and money.

FEATURES & BENEFITS:

- 17 kits for Audi, BMW, and Volkswagen applications
- 1,925,191 VIO in the US and 197,881 VIO in Canada
- All kits include the belt(s), bearing(s), and water pump for the application
- Each kit includes the components needed for a complete service

CRP Automotive
35 Commerce Drive
Cranbury, NJ 08512

Tel. 609.578.4100 800.526.4066
Email: info@crpindustries.com
Web: www.crpautomotive.com



Solution Kits for Vehicles with Timing and Accessory Belts:

CRP Part No.	Applications	VIO US	VIO Canada
RCW0002	AUDI A4 1.8L 1997-98	4,579	561
RCW0003	AUDI A4 1.8L 1999-00; VW PASSAT 1.8L 1998-00	37,208	2,681
RCW0004	AUDI A3 2.0L DIESEL 2010-13; VW GOLF 2.0L DIESEL 2010-14; JETTA 2.0L DIESEL 2009-10	95,778	714
RCW0005	VW BEETLE 2.0L DIESEL 2013-14; GOLF 2.0L DIESEL 2010-14; JETTA 2.0L DIESEL 2009-13	216,107	637
RCW0007	AUDI A3 2.0L 2006-08; TT 2.0L 2008-09; VW EOS 2.0L 2007-08; GTI 2.0L 2006-098; JETTA 2.0L 2006-08; PASSAT 2.0L 2006-08	205,608	23,800
RCW0008	AUDI A4 1.8L 2001; VW PASSAT 1.8L 2002-05	109,828	7,954
RCW0009	AUDI A4 2.8L 1997-01; A6 2.8L 1998-01; VW PASSAT 2.8L 1998-02	30,431	2,444
RCW0010	VW BEETLE 1.9L DIESEL 2004-06; GOLF 1.9L DIESEL 2004-06; JETTA 1.9L DIESEL 2004-05	36,233	16,795
RCW0011	VW JETTA 1.9L DIESEL 2005-06	41,314	17,588

Solution Kits for Vehicles with Accessory Belts Only:

CRP Part No.	Applications	VIO US	VIO Canada
RSW0001	AUDI A4 3.2L 2005-09; A6 3.2L 2005-09	60,339	5,372
RSW0015	BMW 128I 3.0L 2008-13; 323I 2.5L 2006-11 (CAN); 325I / 325XI 2.0L 2006; 328I 3.0L 2007-13; 328XI 3.0L 2007-08; 330I / 330XI 3.0L 2006; 525I / 525XI 3.0L 2006-07; 528I 3.0L 2008-10; 528XI 3.0L 2008; 530I / 530XI 3.0L 2006-07; X3 3.0L 2007-10; X5 3.0L 2007-08; X5 3.0L GAS 2009-10	754,935	83,309
RSW0016	BMW 320I 2.2L 2001-03 (CAN, MX); 323CI 2.5L 2000; 323I 2.5L 1998-00; 325CI / 325I / 325XI 2.5L 2001-03; 330CI / 330I / 330XI 3.0L 2001-03; 525I 2.5L 2001-03; 528I 2.8L 1998-00; 530I 3.0L 2001-03; X5 3.0L 2001-03; Z3 2.5L 2001-02; Z3 3.0L 2001-02	452,253	27,602
RSW0017	BMW 550I 4.8L 2006-10; 650I 4.8L 2006-10; 750I / 750LI 4.8L 2006-08	78,187	3,388
RSW0018	BMW 320I 2.2L 2003-05 (CAN, MX); 325CI 2.5L 2003-06; 325I / 325XI 2.5L 2003-05; 330CI 3.0L 2003-06; 330I / 330XI 3.0L 2003-05; 525I 2.5L 2003; 530I 3.0L 2003; X5 3.0L 2003-06	301,511	24,271
RSW0019	BMW 1 SERIES M 3.0L 2011; 135I 3.0L 2008-10; 335I 3.0L 2007-10; 335IS 3.0L 2011-13; 335XI 3.0L 2007-08	108,205	13,812
RSW0020	BMW 135I 3.0L 2011-13; 335I 3.0L 2011-13; X1 3.0L 2013-15	59,961	6,895
RSW0021	BMW 535I 3.0L 2008-10; 535XI 3.0L 2008	45,963	2,518