

# This Just In!



Updated:  
November 15, 2022

## REIN DCT SERVICE KITS FOR BMW

Data available through [Activant/Epicor](#), [WHI](#), or [ShowMeTheParts.com](#)

Rein Automotive now offers four OE-Quality DCT Transmission Service Kits for Getrag GS7D36SG 7-speed transmissions used in many of BMW's performance platforms on the road today. These vehicles are designed around performance and are normally driven harder on the road, they require more attention, care, and service. A common failure on oil pumps in this transmission can lead to premature failure of the clutch, sensors, and other transmission components from lack of proper lubrication and overheating. All three new Rein kits are held to the highest design standards, comprised of OE-quality parts, and are direct factory replacements for the OE.

- **Rein OE-Quality DCT Clutch Replacement Kit (CRP Part No. TSC0027):** First-to-market, includes o-ring, input shaft seal, and clutch kit
- **Rein OE-Quality DCT Oil Pump Kit (CRP Part No. TSP0028):** First-to-market, includes DCT transmission oil pump and DCT pump installation kit
- **Rein OE-Quality DCT Temperature Sensor (CRP Part No. ELT0086):** Includes temperature sensor and DCT RPM
- **NEW! Rein OE-Quality DCT Clutch Replacement Kit (CRP Part No. TSC0029):** First-to-market, includes o-ring, input shaft seal, and clutch kit

### FEATURES & BENEFITS:

- DCT Service Kits for Getrag GS7D36SG
- Direct OE replacement kits
- Kits include all parts necessary to perform indicated service
- Designed to highest quality standards to avoid costly failures
- 2 year/24,000 mile warranty



CRP Part No. TSC0027



CRP Part No. TSP0028



CRP Part No. ELT0086



**NEW!** CRP Part No. TSC0029

**CRP Automotive**  
35 Commerce Drive  
Cranbury, NJ 08512

Tel. 609.578.4100 800.526.4066  
Email: [info@crpindustries.com](mailto:info@crpindustries.com)  
Web: [www.crpautomotive.com](http://www.crpautomotive.com)



Rein Part No.	OE Reference	Applications	VIO US	VIO CA	ETA Date
<b>TSC0027</b>	28407842841	BMW 135I 3.0L 2011-13; 135IS 3.0L 2013; 335IS 3.0L 2011-13; M2 3.0L 2016-21; M3 3.0L 2015-18; M4 3.0L 2015-20; Z4 3.0L 2009-16	74,695	7,841	Available Now
<b>TSP0028</b>	28107842849 28107842850	BMW 135I 3.0L 2011-13; 135IS 3.0L 2013; 335IS 3.0L 2011-13; M2 3.0L 2016-21; M3 4.0L 2008-13; M3 3.0L 2015-18; M4 3.0L 2015-20; M5 4.4L 2012 (CA, MX); M5 4.4L 2013-16; M6 4.4L 2012-18; M6 GRAN COUPE 4.4L 2014-19; Z4 3.0L 2009-16	110,363	11,169	Available Now
<b>New!</b> <b>TSC0029</b>	28407842841	BMW M3 4.0L 2008-13; M5 4.4L 2013-16; M5 4.4L 2012 (CA, MX); M6 4.4L 2012-18; M6 GRAN COUPE 4.4L 2014-19	34,954	3,378	November 2022
<b>ELT0086</b>	28107842851	BMW 135I 3.0L 2011-13; 135IS 3.0L 2013; 335IS 3.0L 2011-13; M2 3.0L 2016-21; M3 4.0L 2008-13; M3 3.0L 2015-18; M4 3.0L 2015-20; M5 4.4L 2012 (CA, MX); M5 4.4L 2013-16; M6 4.4L 2012-18; M6 GRAN COUPE 4.4L 2014-19; Z4 3.0L 2009-16	110,363	11,169	Available Now