



Remanufactured EPS Racks CRP Part No. ER7040, ER7041, ER7050, ER7051

Applications:

Multiple applications for
Subaru Legacy & Outback 2.5L/3.6L 2015-16
For details, see showmethепarts.com/crp



CRP Part No. ER7040



CRP Part No. ER7041



CRP Part No. ER7050



CRP Part No. ER7051

Subaru OE reference # 34110AL010, 34110AL090, 34110AL000, 34110AL080. First-to-market racks completely remanufactured with all new seals, gaskets, internal bar bushings, motor coupler, bellows and clamps. Electronically tested with vehicle simulation software. Programming not required. Each unit is already serviced to address a Serviced Bulletin issued by Subaru (04-17-17R) regarding concerns of a rattling sound identified as coming from the EPS rack assembly.



Remanufactured EPS Racks CRP Part No. ER9110 & ER9130

Applications:

Multiple applications for Audi
For details, see showmethепarts.com/crp



CRP Part No. ER9110



CRP Part No. ER9130

Audi OE reference # 8K1423055AN & 8R1423055AF. First-to-market rack replacements for option QZ7- Standard power steering. All internal seals and gaskets are replaced and new bellows, clamps, and heat shield mat are installed. ECU plug connector and torque sensor harness are inspected and replaced if necessary. Multiple inspection and testing steps are taken to ensure proper operation.



Turbo Coolant Supply Hose CRP Part No. CHT0687

Applications:

Multiple applications for BMW
For details,
see showmethепarts.com/crp



BMW OE reference # 11537558901. Designed as direct-fit replacement to ensure trouble-free installation.



Air Intake Hoses CRP Part No. ABV0025 & ABV0026

Applications:

Mercedes-Benz
GLK350 3.5L 2010-12



CRP Part No. ABV0025



CRP Part No. ABV0026

Mercedes OE reference # 2720902882 & 2720902982. ABV0025 is passenger side, ABV0026 is driver side. Both are designed to match OE design specifications.