



TechSelect Turbo Mounting Kit CRP Part No. TRK0020

Applications:

Multiple applications for BMW
For details, see showmetheparts.com/crp



First-to-market TechSelect Turbo Kits include all OE components needed for turbocharger replacement, such as hoses, hardware, gaskets, brackets, and heat shielding. Made to handle the demanding conditions of turbocharger systems and provide a trouble-free installation.



Engine Coolant Reservoir CRP Part No. EPT0259

Applications:

Multiple applications for BMW B46 engines
For details, see showmetheparts.com/crp



Rein OE quality engine coolant reservoir produced from virgin plastic with no regrind to prevent cracking from heat cycles to ensure durability. Direct fit for easy installation.



Engine Coolant Reservoir CRP Part No. EPT0257

Applications:

Volvo C40 2022-23; C40 Recharge 2022-24;
XC40 2.0L 2019-22; XC40 Recharge 2021-24



First-to-market OE quality engine coolant reservoir produced from virgin plastic with no regrind to prevent cracking from heat cycles to ensure durability. Direct fit for easy installation.



New HPS Rack & Pinion CRP Part No. 3310N

Applications:

Multiple applications for BMW
For details, see showmetheparts.com/crp



New HPS rack and pinion supplied with inner tie rods and new bellows secured by OE stainless steel clamps to keep dirt and debris out, preventing premature failure. Matches OE design specifications. Sold without core charge.



Reman EPS Rack & Pinion CRP Part No. ER4131

Applications:

Cadillac Escalade 2015-16; Escalade ESV
2015-16; Chevrolet Suburban 2015-16;
Tahoe 2015-16; GMC Yukon 2015-16; Yukon XL 2015-16



Remanufactured EPS racks are rebuilt, tested, and certified, ensuring OE performance. Wear components and drive belts are replaced, balanced, and tensioned to OE specifications. Programming requires an SAE J2534 device with OEM software (subscription needed).



Reman HPS Rack & Pinion CRP Part No. 3311

Applications:

BMW X5 2004-06



HPS rack is remanufactured with OE grade, high temperature seals and O-rings for increased durability and performance. 100% hydraulically tested for pressure and flow. Rack supplied with inner tie rods, new bellows secured by OE stainless steel clamps, preventing premature failure.

ECAT data may not be available for parts shown for 90 days after initial announcement.


**FOR MORE INFORMATION CALL 800.526.4066 AND SPEAK WITH A CRP REPRESENTATIVE
OR VISIT CRPAUTOMOTIVE.COM**



New HPS Pump
CRP Part No. 5767N

Applications:

BMW M3 2001-06; Z3 2001-06



New HPS pump engineered to meet or exceed OE specifications. Return pipe included. It is highly recommended to replace steering fluid reservoir when replacing pump. Clogged reservoirs can starve the replacement pump. Sold without core charge.

ECAT data may not be available for parts shown for 90 days after initial announcement.

**FOR MORE INFORMATION CALL 800.526.4066 AND SPEAK WITH A CRP REPRESENTATIVE
OR VISIT CRPAUTOMOTIVE.COM**